



Work Safety Alert Fall from an Elevated Metal Pallet

- 1. Date of Accident : April 2013
- 2. Place of Accident : A warehouse in Yuen Long

3. Summary :

A worker, while standing on a metal pallet raised by a forklift truck to replace the rain water drainage at the ceiling of a warehouse, fell 4 meters to his death.

4. Work Safety Alert for Contractors/Employers :

To prevent any person from falling from height, contractors/employers undertaking work at height at ceilings should:

- conduct risk assessments and formulate appropriate safe working procedures for the work;
- use suitable working platforms as safe means of access and support for the work and prohibit the use of forklift trucks for the purposes;
- display prominent warning notices to alert workers of the falling hazard; and
- implement effective monitoring system to ensure that the above safety measures are strictly followed.

5. Reference :

- Five Steps to Risk Assessment¹
- <u>Safe Systems of Work</u>¹





• <u>Guidance Notes on Safe Use of Power-operated Elevating Work Platforms</u>¹

DISCLAIMER

This Work Safety Alert ("the Alert") is issued at the earliest possible opportunity after a serious accident with a view to drawing the attention of interested parties to the general safety precautionary measures necessary to protect people engaging in similar work activities. The material contained in the Alert constitutes general guidance only. It does not reduce, limit, or replace, any legal obligations upon any person to comply with any statutory duties under relevant legislation. Users such as Managers and Supervisors should make their own evaluation of the information contained in the Alert to determine if it can be applied to their own situations and practices. The Labour Department does NOT accept any responsibilities for any loss or damage resulting from the use of or failure to use of the information on the Alert.

¹ Click to view the document