



## Work Safety Alert Fall from a Bamboo Scaffold

- 1. Date of Accident : October 2013
- 2. Place of Accident : A building construction site in Tseung Kwan O
- 3. Summary :

A worker fell to his death from 35/F level down to 23/F while he was engaged in removing concrete debris on a platform of the scaffold at the external wall.

## 4. Work Safety Alert for Contractors/Employers :

Where construction work activities may give rise to debris or waste materials, contractors/employers should:

- avoid accumulation of debris or waste materials on scaffolds;
- avoid work-at-height at the external wall to remove the debris or waste materials on scaffolds;
- where work-at-height to remove the debris or waste materials on scaffolds is required:
- conduct risk assessments, with due consideration of the loading capacity of the scaffolds in particular, and formulate appropriate safe working procedures for the work;
- ensure that the scaffolds are securely supported and properly maintained;
- > ensure that the scaffolds are inspected and certified safe by a





competent person;

- provide and maintain suitable and adequate safe access to and egress from every place of work;
- ensure the use of suitable working platforms for the work where practicable;
- ensure that the working platforms are not overloaded and that no shock loading on the working platforms is allowed;
- where use of the working platforms is impracticable, ensure that suitable and sufficient fall protection devices connected with proper anchorages are provided and maintained and ensure the use of the fall protection devices by workers;
- implement effective monitoring and supervision to ensure that the above safety measures are strictly followed.

## 5. Reference :

- <u>A Guide to the Provisions for Safe Places of Work under Part VA of the</u> <u>Construction Sites (Safety) Regulations</u><sup>1</sup>
- <u>Code of Practice for Bamboo Scaffolding Safety</u><sup>1</sup>
- <u>Guidance Notes on Classification and Use of Safety Belts and their</u> <u>Anchorage Systems</u><sup>1</sup>

\*\*\*\*\*

<sup>&</sup>lt;sup>1</sup> Click to view the document



職業安全及健康部 Occupational Safety and Health Branch 勞工處 Labour Department



## **DISCLAIMER**

This Work Safety Alert ("the Alert") is issued at the earliest possible opportunity after a serious accident with a view to drawing the attention of interested parties to the general safety precautionary measures necessary to protect people engaging in similar work activities. The material contained in the Alert constitutes general guidance only. It does not reduce, limit, or replace, any legal obligations upon any person to comply with any statutory duties under relevant legislation. Users such as Managers and Supervisors should make their own evaluation of the information contained in the Alert to determine if it can be applied to their own situations and practices. The Labour Department does NOT accept any responsibilities for any loss or damage resulting from the use of or failure to use of the information on the Alert.